

107




FIGURE 1

TI-35367

1 of 2

Slow discharge due to leakage.

